


Wafer mounted 4" above furnace. TC failure due to test fixture separating from furnace, not an issue with the furnace itself.

RADAK II Cool-Down Curve from 1500°C





Radak II New Style Soak @ 1700C

